


Tested Superiority




See how research backs this unique system

Korea Lotte Hotel

December 31st, 2004



Water supply pump 10K_g/m²



ST-250L

Tested Superiority



See how research backs this unique system

Korea Lotte Hotel



Pipe-inside Photo taken with endoscope




Pipe, inside



Pipe maintenance section



Pipe Cross section



Installed S T-250 L against the wall